

NOTE: In the event of removing the turntable motor cover this part should be refitted using screw connection: 5028 14 53-00/6 (710)