




Mat. – Nr. – Konstante
3740

Gebrauchsanweisung
58 4745 (he) V01
58 4746 (en) V01
59 2037 (en) V02
59 2038 (ru) V02
59 2040 (he) V02

Aufstellanweisung
58 4718 (he) V01
58 4400 (en) V01
58 4401 (he) V02

Programmtabelle
52 7885 (he) V01
52 7888 (en) V01
59 2041 (en) V02
59 2042 (ru) V02
59 2043 (he) V02

1) Blende kompl.
36 0928
(en) V01
44 0975
(symbole) V02

Zubehör:


Bodenbefestigung
WMZ2200


Entkalker
46 0038



Mat. – Nr. – Konstante
3740


1) 2 x pro Gerät





Mat. – Nr. – Konstante
3740

- 1) 26 3372
- 2) 26 3373
- 3) 16 5983
- 4) 26 3395
- 5) 16 5984
- 6) 48 0138
- 7) kompl.
- 8) 16 5978



Mat. – Nr. – Konstante
3740